

Software Changes and Validation Summary

Control Software Update

505DR (Control Part Numbers: 8200-1330, 8200-1331)

Application Software Updates

GAP Application 5418-7833, Revision D

GUI Application 5418-7833, Revision D

June/8/2026 - Pkumar

The table below provides a detailed description of the application software changes that have been implemented and validated as part of this release.

Type	Issue ID	Title/Issue
Action Item	171662	Model Check logic to be check and improve.
Action Item	169510	Protech GII integration as Woodward Link
Feature	165106	Add options for 'Redundant' Trip discrete input signals
Action Item	162785	Act output spiking when exiting CNFG mode (IOLOCK)
Feature	162191	Header color for calibration mode doesn't work on unit not operated.
Feature	161231	additional screen for communication #2 on RemoteView
Bug	159451	Address mismatch on "Redundancy Overview - Boolean Input" page
Bug	157946	AI Chan1 Inhibit XFER different from other channels
Bug	156499	Manual Adjust key and Goto Value for RTCNet AO RTC26 Chan1 doesn't work correctly.
Feature	147892	Add I/O menu options to support interfacing to a TTV, and options for VS-GI
Bug	173260	GUI screen can access only in IO lock mode for SPC
Action Item	173247	Add caution for power interruption while resetting