



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **DE/TUR/QAR11.0002/07** Page 1 of 2

QAR Free Ref. No.: **125138260** Status:**Issued**

Details of change: Re-Certification Date of issue:**2022-04-11**
 Location in Loveland removed
 Ex i removed Valid until:**2025-04-30**

Site(s) audited: **Woodward, Inc.** Audit date:**2022-03-16**
 1041 Woodward Way
 Fort Collins, CO 80524
United States of America

Woodward, Inc.
 1000 East Drake Road
 Fort Collins, CO 80525
United States of America

Issuing ExCB: **TUR - TUV Rheinland Industrie Service GmbH**

Manufacturer: **Woodward, Inc.**
 1041 Woodward Way
 Fort Collins, Colorado 80524

Location of Manufacturer: **United States of America**

Product information: Industrial Valves, Actuators, Controls

Protection concept: **Ex d Ex e Ex m Ex n**

Related QARs:

DE/TUR/QAR11.0002/00	DE/TUR/QAR11.0002/01	DE/TUR/QAR11.0002/02
DE/TUR/QAR11.0002/03	DE/TUR/QAR11.0002/04	DE/TUR/QAR11.0002/05
DE/TUR/QAR11.0002/06		

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEX CSA 11.0005X issue: 0	IECEX CSA 11.0013X issue: 0	IECEX CSA 11.0017X issue: 0
IECEX CSA 11.0017X issue: 1	IECEX CSA 11.0017X issue: 2	IECEX CSA 11.0017X issue: 3
IECEX CSA 11.0017X issue: 4	IECEX CSA 11.0017X issue: 5	IECEX CSA 11.0017X issue: 6
IECEX CSA 12.0013X issue: 0	IECEX CSA 12.0013X issue: 1	IECEX CSA 12.0013X issue: 2
IECEX CSA 12.0013X issue: 3	IECEX CSA 13.0021X issue: 0	IECEX CSA 13.0041 issue: 0
IECEX CSA 13.0041X issue: 1	IECEX CSA 13.0041X issue: 2	IECEX CSA 13.0041X issue: 3
IECEX CSA 13.0041X issue: 4	IECEX CSA 13.0041X issue: 5	IECEX CSA 13.0041X issue: 6
IECEX CSA 13.0041X issue: 7	IECEX CSA 14.0012X issue: 0	IECEX CSA 14.0012X issue: 1
IECEX CSA 14.0013X issue: 0	IECEX CSA 14.0013X issue: 1	IECEX CSA 14.0013X issue: 2
IECEX CSA 14.0019X issue: 0	IECEX CSA 14.0019X issue: 1	IECEX CSA 14.0019X issue: 2
IECEX CSA 14.0047X issue: 0	IECEX CSA 14.0047X issue: 1	IECEX CSA 14.0055X issue: 0
IECEX CSA 14.0056X issue: 0	IECEX CSA 14.0056X issue: 1	IECEX CSA 15.0009 issue: 0
IECEX CSA 15.0009X issue: 1	IECEX CSA 15.0015X issue: 0	IECEX CSA 15.0015X issue: 1
IECEX CSA 15.0015X issue: 2	IECEX CSA 15.0016X issue: 0	IECEX CSA 15.0020X issue: 0
IECEX CSA 15.0020X issue: 1	IECEX CSA 15.0020X issue: 2	IECEX CSA 15.0020X issue: 3
IECEX CSA 15.0020X issue: 4	IECEX CSA 15.0020X issue: 5	IECEX CSA 15.0022X issue: 0
IECEX CSA 15.0022X issue: 1	IECEX CSA 15.0031X issue: 0	IECEX CSA 15.0031X issue: 1
IECEX CSA 15.0031X issue: 2	IECEX CSA 15.0032X issue: 0	IECEX CSA 15.0032X issue: 1



IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/TUR/QAR11.0002/07**

Page 2 of 2

Related Certificates for previous versions (continued):

IECEX CSA 15.0050X issue: 0
IECEX CSA 15.0052X issue: 2
IECEX CSA 17.0004X issue: 0
IECEX CSA 18.0038X issue: 0
IECEX CSA 19.0038X issue: 0
IECEX ETL 15.0025X issue: 0
IECEX ETL 16.0010X issue: 0
IECEX LCI 08.0043 issue: 1
IECEX LCI 12.0011X issue: 0
IECEX LCIE 12.0001X issue: 0
IECEX TUR 11.0014X issue: 3
IECEX TUR 15.0024X issue: 0

IECEX CSA 15.0052X issue: 0
IECEX CSA 16.0037X issue: 0
IECEX CSA 18.0028X issue: 0
IECEX CSA 18.0039X issue: 0
IECEX CSA 19.0038X issue: 1
IECEX ETL 15.0025X issue: 1
IECEX ETL 18.0002X issue: 0
IECEX LCI 10.0024 issue: 1
IECEX LCI 12.0011X issue: 1
IECEX TUR 11.0012X issue: 0
IECEX TUR 11.0014X issue: 4

IECEX CSA 15.0052X issue: 1
IECEX CSA 16.0037X issue: 1
IECEX CSA 18.0028X issue: 1
IECEX CSA 18.0043X issue: 0
IECEX CSA 19.0038X issue: 2
IECEX ETL 15.0025X issue: 2
IECEX ETL 18.0002X issue: 1
IECEX LCI 12.0010X issue: 0
IECEX LCI 12.0011X issue: 2
IECEX TUR 11.0014X issue: 1
IECEX TUR 13.0013X issue: 0

Comments: