

Software Changes and Validation Summary

**Peak200 (control p/ns 8200-1500,01,02,03,04,05,06,07,08,09)
GAP Application 5418-7275 D to Rev E**

The following table describes the application software changes implemented and tested in this release.

Issue ID	Issue Type	TITLE
Bug	136568	Disable screen saver does not fully work
Feature	150175	Annunciate reasons for Remote Speed Setpoint Inhibited
Feature	147102	Reduce OSPD - nuisance trip on real starts after testing
Feature	139554	Add 'no Trip' option to Normal Stop sequence
Manual Only	147321	Manual Update - add info about ACT output action in HW SIM mode
Manual Only	144905	Manual Update -Rate group is not configurable as a standard product of Peak 200
Action Item	171826	.out stopped condition on interrupted power supply while resetting, Noted added to the resetting pop up “Don’t interrupt Power supply”