

October 2004 – September 2006

**NOTICE TO USERS OF PRATT & WHITNEY ENGINES
WITH WOODWARD ACCESSORIES**

The attached list of Operation-Maintenance manuals for Woodward accessories used on Pratt & Whitney engines includes price and order information. The price of manuals mailed outside the continental United States includes a fee (each) for customs and handling.

Manuals and revisions are issued in **CD format only**. Your order initiates a subscription which includes revisions and service bulletins for three years from receipt of order.

Full payment must accompany your order.

Please direct all communications to:

WOODWARD AIRCRAFT ENGINE SYSTEMS
Attn: Customer Service
One Woodward Way
Rockton, IL 61072-0405
USA

Tel: 815 624-4400

Fax: 815 624-1926



**OPERATION-MAINTENANCE
MANUALS
FOR WOODWARD ACCESSORIES
ON PRATT & WHITNEY ENGINES**

WOODWARD AIRCRAFT ENGINE SYSTEMS

Attn: Customer Support
One Woodward Way
Rockton, IL 61072-0405
Tel: 815 624-4400
Fax: 815 624-1926

PART NO.	ATA & MANUAL NO.	SUBSCRIPTION PRICE			
		Domestic New	Foreign New	Domestic Renewal	Foreign Renewal
TURBOPROP GOVERNORS					
8210-002M;8210-002N;8210-002P;8210-002R; 8210-002S;8210-002T;8210-002U;8210-002V; 8210-002W;8210-002Y;8210-003B;8210-003C; 8210-003D;8210-003E;8210-003F;8210-003G; 8210-003H;8210-003J;8210-003K;8210-003L; 8210-003M;8210-004;8210-004B;8210-004C; 8210-004D;8210-004E;8210-004F;8210-004G; 8210-004H;8210-004J;8210-004K;8210-004L; 8210-004M;8210-006;8210-006A;8210-006B; 8210-006C;8210-006D;8210-006E;8210-007A; 8210-007B;8210-007C;8210-008C;8210-008D; 8210-008E;8210-009;8210-009A;8210-009B; 8210-009C;8210-033;8210-033A;8210-033B; 8210-033C	61-20-01 (60015) ALSO SEE PN'S UNDER 61-20-14 (60044) 61-20-15 (60045) AND 61-20-19 (60046)	N/A	N/A	N/A	N/A
8210-040D;8210-040E;8210-040F;8210-040G; 8210-040H;8210-041;8210-041A;8210-041B; 8210-041C;8210-041D;8210-042;8210-042A; 8210-042B;8210-042C;8210-042D; 8210-042E	61-20-04 (60018)	\$500.00	\$550.00	\$300.00	\$350.00
8210-035;8210-035A;8210-035B;8210-035C; 8210-035D;8210-035E;8210-134;8210-134A	61-20-05 (60019)	\$500.00	\$550.00	\$300.00	\$350.00
8210-024B;8210-024D;8210-024E;8210-024F; 8210-024G;8210-024H;8210-025;8210-025D; 8210-025E;8210-025F;8210-025G;8210-027; 8210-027A;8210-027B;8210-027C;8210-027D	61-20-06 (60020)	\$500.00	\$550.00	\$300.00	\$350.00
8210-034E;8210-034F;8210-034G;8210-034H; 8210-034J;8210-034K;8210-034L;8210-046D; 8210-046E;8210-046F;8210-046G;8210-046H; 8210-146; 8210-146A;8210-146B;8210-210; 8210-212;8210-212A;8210-212B; 8210-212C; 8210-212D;8210-212E;8210-212F;8210-212G; 8210-212H	61-20-10 (60021)	\$500.00	\$550.00	\$300.00	\$350.00
8210-133;8210-133A;8210-133B;8210-133C; 8210-209;8210-209A;8210-209B;8210-209C; 8210-209D	61-20-11 (60022)	\$500.00	\$550.00	\$300.00	\$350.00
8210-135B;8210-0135E;8210-135F	61-20-12 (60023)	\$500.00	\$550.00	\$300.00	\$350.00

Products and data listed in this publication are subject to change without prior notification.
PWC Engine Woodward Accessories – Oct 2004 – Sep 2006

Rev 2006



PART NO.	ATA & MANUAL NO.	SUBSCRIPTION PRICE			
		Domestic New	Foreign New	Domestic Renewal	Foreign Renewal
TURBOPROP GOVERNORS Continued					
8210-002AA;8210-002AB;8210-002AC; 8210-002AD;8210-002AE;8210-003N; 8210-003P;8210-003R;8210-003T;8210-003U; 8210-004N; 8210-004P;8210-004R;8210-004T; 8210-004U	61-20-14 (60044)	\$500.00	\$550.00	\$300.00	\$350.00
8210-006F;8210-006G;8210-006H;8210-006J; 8210-007D;8210-007E;8210-007F;8210-007G	61-20-15 (60045)	\$500.00	\$550.00	\$300.00	\$350.00
8210-188A;8210-188B;8210-189B; 8210-189C; 8210-191;8210-191A;8210-191B; 8210-191C; 8210-192;8210-192A;8210-198; 8210-198A; 8210-198B;8210-199;8210-199A; 8210-199B; 8210-199C;8210-199D;8210-201; 8210-388; 8210-388A;8210-389;8210-389A; 8210-391; 8210-391A;8210-391B;8210-392; 8210-392A; 8210-398;8210-398A; 8210-399A; 8210- 400A;8210-401A;8210-401B; 8210-402A; 8210- 404A	61-20-18 (60042)	\$500.00	\$550.00	\$300.00	\$350.00
8210-009D;8210-009E;8210-009F;8210-009G; 8210-033D;8210-033E;8210-033F	61-20-19 (60046)	\$500.00	\$550.00	\$300.00	\$350.00
8210-193A;8210-393;8210-393A;8210-403; 8210-403A	61-20-21 (60057)	\$500.00	\$550.00	\$300.00	\$350.00
8210-137;8210-137A;8210-137B;8210-137C; 8210-137D;8210137E;8210-137G;8210-137H	61-20-23 (60074)	\$500.00	\$550.00	\$300.00	\$350.00
8210-410	61-20-35 (60152)	\$500.00	\$550.00	\$300.00	\$350.00
8210-406;8210-407;8210-408;8210-409; 8210-411	61-20-36 (60153)	\$500.00	\$550.00	\$300.00	\$350.00

OVERSPEED GOVERNORS					
210618;210651	61-20-03 (60017)	\$500.00	\$550.00	\$300.00	\$350.00
8210-060J;8210-060K;8210-061;8210-061G; 8210-061H;8210-064;8210-064C;8210-064D; 8210-068	61-20-07 (60003)	\$500.00	\$550.00	\$300.00	\$350.00
8210-160;8210-160A;8210-160B;8210-160C; 8210-160D;8210-160E;8210-160F;8210- 161;8210-161A; 8210-161B;8210-161C;8210- 161D;8210-161E;8210-161F;8210-164; 8210- 164A;8210-164B;8210-164C;8210-164D;8210- 164E;8210-167;8210-167A;8210-167B;8210- 167C; 8210-167D;8210-167E;8210-168;8210- 168A;8210-168B;8210-290A;8210-290B	61-20-16 (60036)	\$500.00	\$550.00	\$300.00	\$350.00

Products and data listed in this publication are subject to change without prior notification.
PWC Engine Woodward Accessories – Oct 2004 – Sep 2006

Rev 2006



PART NO.	ATA & MANUAL NO.	SUBSCRIPTION PRICE			
		Domestic New	Foreign New	Domestic Renewal	Foreign Renewal
AUTOFEATHER VALVES					
8905-002C;8905-004;8905-006A	61-20-02 (60016)	\$150.00	\$180.00	\$80.00	\$110.00

PROPELLER INTERFACE UNIT					
8210-502;8210-502A	61-20-34 (60102)	\$500.00	\$550.00	\$300.00	\$350.00

PUMPS					
8210-076;8210-076A;8210-076C;8210-076D; 8210-076E	61-20-08 (60004)	\$500.00	\$550.00	\$300.00	\$350.00
8210-077H;8210-079;8210-178;8210-178A; 8210-179;8210-179A	61-20-13 (60027)	\$500.00	\$550.00	\$300.00	\$350.00
8210-176;8210-176A;8210-176B;8210-176C	61-20-17 (60037)	\$500.00	\$550.00	\$300.00	\$350.00
8210-180A;8210-180B;8210-180C;8210-180D; 8210-181A;8210-181B;8210-184;8210-286	61-20-20 (60051)	\$500.00	\$550.00	\$300.00	\$350.00
8210-183	61-20-22 (60058)	\$500.00	\$550.00	\$300.00	\$350.00

FUEL CONTROLS					
8061-310;8061-317;8061-319;8061-319A; 8061-327;8061-331;8061-331A	73-20-02 (60008)	\$500.00	\$550.00	\$300.00	\$350.00
8061-320;8061-320A;8061-320B;8061-320C; 8061-320D;8061-320E;8061-329;8061-329A; 8061-329B;8061-332;8061-332A;8061-332B; 8061-332C	73-20-03 (60034)	\$500.00	\$550.00	\$300.00	\$350.00
8063-020;8060-020B;8063-020C;8060-020D; 8060-020G;8063-021;8063-021A;8063-021B; 8063-021E;8063-022;8063-022A;8063-022B; 8063-023;8063-023A;8063-023B;8063-024A; 8063-024B;8063-027	73-20-04 (60041)	\$500.00	\$550.00	\$300.00	\$350.00
8063-030;8063-030A;8063-034;8063-035; 8063-037;8063-037B;8063-038A;8063-050; 8063-050A; 8063-051;8063-052A;8063- 060A;8063-061A	73-20-05 (60054)	\$500.00	\$550.00	\$300.00	\$350.00
8063-108A;8063-109;8063-110	73-20-06 (60055)	\$500.00	\$550.00	\$300.00	\$350.00
8061-305;8061-305B;8061-315A;8061-315C; 8061-351D;8061-318;8061-318B;8061-328; 8061-328A;8061-328B;8061-340	73-20-07 (60071)	\$500.00	\$550.00	\$300.00	\$350.00
8061-311;8061-316;8061-321;8061-326; 8061-330;8061-330A;8061-333;8061-334	73-20-08 (60067)	\$500.00	\$550.00	\$300.00	\$350.00

Products and data listed in this publication are subject to change without prior notification.
PWC Engine Woodward Accessories – Oct 2004 – Sep 2006

Rev 2006



PART NO.	ATA & MANUAL	SUBSCRIPTION PRICE			
		New	New	Renewal	Renewal
FUEL CONTROLS Continued					
8063-031C;8063-036;8063-040;8063-041; 8063-041A;8063-042A	73-20-09 (60068)	\$500.00	\$550.00	\$300.00	\$350.00
8063-032;8063-009B	73-20-11 (60073)	\$500.00	\$550.00	\$300.00	\$350.00
8063-000A;8063-000C;8063-000D;8063-000F; 8063-000G;8063-001;806-001A;8063-001B; 8063-001D;8063-001E;8063-002;8063-002A; 8063-002B;8063-003;8063-003A;8063-003B; 8063-004;8064-004A;8063-005;8063-005A; 8063-005B;8063-005C	73-20-12 (60088)	\$500.00	\$550.00	\$300.00	\$350.00
8063-008;8063-010;8063-010B;8063-011; 8063-011A;8063-011B;8063-011F;8063-012; 8063-012A;8063-012B;8063-012C;8063-013; 8063-013D;8063-015	73-20-13 (60089)	\$500.00	\$550.00	\$300.00	\$350.00
8061-314A;8061-314B;8061-322;8061-324	73-20-20 (60107)	\$500.00	\$550.00	\$300.00	\$350.00

PUBLICATIONS ORDER FORM ON FOLLOWING PAGE

Products and data listed in this publication are subject to change without prior notification.
PWC Engine Woodward Accessories – Oct 2004 – Sep 2006

Rev 2006

WOODWARD GOVERNOR COMPANY

DATE: _____

PRATT & WHITNEY ENGINE ACCESSORIES OVERHAUL MANUALS ORDER FORM

Woodward Aircraft Engine Systems

Attn: Customer Support

One Woodward Way, Rockton, IL 61072-0405

Fax: 815 624-1926

S O L D T O	Name:	S H I P T O	Name:
	Address		Address
	Ordered by		Ordered by

MANUAL NO.	QTY NEW	PRICE DOMESTIC	PRICE FOREIGN	QTY RENEWAL	PRICE DOMESTIC	PRICE FOREIGN	TOTAL
60003		\$500.00	\$550.00		\$300.00	\$350.00	\$
60004		\$500.00	\$550.00		\$300.00	\$350.00	\$
60008		\$500.00	\$550.00		\$300.00	\$350.00	\$
60016		\$150.00	\$180.00		\$80.00	\$110.00	\$
60017		\$500.00	\$550.00		\$300.00	\$350.00	\$
60018		\$500.00	\$550.00		\$300.00	\$350.00	\$
60019		\$500.00	\$550.00		\$300.00	\$350.00	\$
60020		\$500.00	\$550.00		\$300.00	\$350.00	\$
60021		\$500.00	\$550.00		\$300.00	\$350.00	\$
60022		\$500.00	\$550.00		\$300.00	\$350.00	\$
60023		\$500.00	\$550.00		\$300.00	\$350.00	\$
60027		\$500.00	\$550.00		\$300.00	\$350.00	\$
60034		\$500.00	\$550.00		\$300.00	\$350.00	\$
60036		\$500.00	\$550.00		\$300.00	\$350.00	\$
60037		\$500.00	\$550.00		\$300.00	\$350.00	\$
60041		\$500.00	\$550.00		\$300.00	\$350.00	\$
60042		\$500.00	\$550.00		\$300.00	\$350.00	\$
60044		\$500.00	\$550.00		\$300.00	\$350.00	\$
60045		\$500.00	\$550.00		\$300.00	\$350.00	\$
60046		\$500.00	\$550.00		\$300.00	\$350.00	\$
60051		\$500.00	\$550.00		\$300.00	\$350.00	\$
60054		\$500.00	\$550.00		\$300.00	\$350.00	\$
60055		\$500.00	\$550.00		\$300.00	\$350.00	\$
60057		\$500.00	\$550.00		\$300.00	\$350.00	\$
60058		\$500.00	\$550.00		\$300.00	\$350.00	\$
60067		\$500.00	\$550.00		\$300.00	\$350.00	\$
60068		\$500.00	\$550.00		\$300.00	\$350.00	\$
60071		\$500.00	\$550.00		\$300.00	\$350.00	\$
60073		\$500.00	\$550.00		\$300.00	\$350.00	\$
60074		\$500.00	\$550.00		\$300.00	\$350.00	\$
60088		\$500.00	\$550.00		\$300.00	\$350.00	\$
60089		\$500.00	\$550.00		\$300.00	\$350.00	\$
60102		\$500.00	\$550.00		\$300.00	\$350.00	\$
60107		\$500.00	\$550.00		\$300.00	\$350.00	\$
60152		\$500.00	\$550.00		\$300.00	\$350.00	\$
60153		\$500.00	\$550.00		\$300.00	\$350.00	\$
TOTAL ENCLOSED							\$

Manuals and revisions in CD format only. Your order initiates a new subscription which includes revisions and service bulletins for three years from receipt of order. Full payment must accompany each order.

Products and data listed in this publication are subject to change without prior notification.

PWC Engine Woodward Accessories – Oct 2004 – Sep 2006

Rev 2006