



TecJet 52

Product Change

The TecJet 52 using the F-Series 35-pins actuator has been an important offering from Woodward for many years that Woodward had supported through many rounds of obsolescence management. Due to the volatility of the semiconductor supply chain market, declining demand for non-RoHs components, and an already available RoHs compatible solution (100% backwards compatible), the non-RoHs versions are being inactivated.

Product Support Schedule

Last Time Buy – December 31, 2023

- Limited repairs
- Limited sales based on component availability
- Not recommended for new designs

Last Time Buy Shipment – June 30, 2024

- Limited repairs – based on component availability
- Limited sales of accepted orders by LTB date
- Replacement product. For upgrades, contact Woodward Services team.

Product Inactivation – September 30, 2025

- Limited repairs – based on available components / tools / process
- Replacement product. For upgrades, contact Woodward Services team.

Woodward will continue to fully support the product while under its original factory warranty.

Replacement Options

The TecJet 52 (generation 2) RoHs variant is 100% compatible with the current non-RoHs versions.

Customer Action

Prior to December 31, 2023, contact your local Woodward representative for Last Time Buy opportunities OR to discuss available upgrade/migration products.

Note – Component obsolescence from electronic manufacturers can present a challenge to post-life support plans. Woodward strives to hold inventory or look for alternative parts when components that are actually used are no longer available. However, there are times when components simply cannot be obtained and where sufficient Last Time Buys cannot be made. Unfortunately, in these cases Woodward cannot guarantee the rationalization support plan.

Affected Items

Non-RoHs (50+ or 52 G1)	Replaced by Non-RoHs, G2	Replaced by RoHs Version, G2	Remarks
For Reference Only (inactive)	To be Inactivated	For New Designs	
	468-2639 / 20R-5665 (June '24)	525-8021 / 20R-9772	Customer protocol
	472-8429 / 20R-5664 (June '24)	506-8199 / 20R-9664	Customer protocol
8407-526 (Dec. '23)	8407-540 (Dec. '23)	8407-605	EGS-01 protocol
8407-527 (Dec. '23)	8407-534 (June '24)	8407-603	EGS-02 protocol
8407-528 (Dec. '23)	Not applicable	Not available	
8407-532 (Dec. '23)	Not applicable	Not available	
	8407-535 (June '24)	8407-604	
8407-601 (Dec. '23)	8407-536 (June '24)	8407-636	Customer protocol
	8407-547 (June '24)	8407-647	
8407-600 (Dec. '23)		8407-537	
8407-602 (Dec. '23)		8407-537	

Copyright © Woodward, Inc. 2023
All Rights Reserved



WOODWARD

PO Box 1519, Fort Collins CO 80522-1519, USA
1041 Woodward Way, Fort Collins CO 80524, USA
Phone +1 (970) 482-5811 • Fax +1 (970) 498-3058

Email and Website—www.woodward.com

Woodward has company-owned plants, subsidiaries, and branches, as well as authorized distributors and other authorized service and sales facilities throughout the world.

Complete address / phone / fax / email information for all locations is available on our website.